INVESTIGATION REPORT DEPARTMENT OF COUNTY ENGINEER BUILDING AND SAFETY DIVISION COUNTY OF LOS ANGELES

Location of Problem	15536	Crmanita (m
Locality	Bardena	
Description of Problem	unsales	Block Wall
Between	house	
Chiner: Gloric	a Megal	
17042	Casimór Ave	>
Torran		329-2453
Requested by	MOJOROVICH	Phone 644-2574
Address /55	36 ERMANITH	·
Received by Helen	<u> </u>	Date3-/5-82
Referred to B. MC	Bon	
Report of Investigation	: Block wa	11 broken and in
danger of fall	ling - Kemou	e or repair within
30 days - Nulse	on	
		/ 1
5/18/82 Kef	pair work a	empleted_ Melson
Investigator Melson	7Title	Date
Copy Sent To	Title	Date
Report Phoned To	Title	Date